

Recall — MY21–25 Malibu/Axis Tri-Axle Boat Trailer — Brake Lines

Dear Valued Malibu/Axis Dealer,

This letter is an early notification to inform you that one or more Malibu and/or Axis boat trailers that you sold and/or currently have in your inventory have been identified as having a potential safety issue due to their configuration based on date of manufacture.

Our quality assurance team has discovered that the brake lines installed on MY21–25 Malibu and Axis trailers (tri-axle only; single/tandem are not affected) built after September 21st, 2020, may be prone to unintended stress, potentially resulting in failure during operation due to the way the brake lines were routed and secured to the axles at time of manufacture. **To avoid potential trailer and/or boat damage, all affected trailers should be fitted with new brake lines in an updated configuration.**

Again, this is an early notification. Customers will be notified by Malibu of this recall via letter within the next two weeks. We are in the process of acquiring parts and preparing replacement brake line kits. Your Technical Representative will reach out to you directly with a list of affected units associated with your dealership.

Please refer to the Service Bulletin on the next page for the necessary information to address this matter, including work instructions, part numbers and ordering instructions, and the flat rate time allowed for repair.

If you have questions, please contact your Technical Representative.

We apologize for any inconvenience. Malibu Boats always strives to provide our customers with world-class support and ensure their long-term enjoyment of their boats and trailers. We thank you for your patience and cooperation in this matter.

Sincerely,
Malibu Boats

**SB Number:**

RB_02MC_070725

Topic:

Trailer Brake Lines

Models Affected:MY21–25 Malibu and Axis
Tri-Axle Trailers**Flat Rate Time:**

3.75 hrs (if manual bleeding)

3.00 hrs (if using power
bleeder)

5075 Kimberly Way
Loudon, TN 37774
865.458.5478

SERVICE BULLETIN - RECALL

This is a mandatory service bulletin—please read and follow all instructions.

Our quality assurance team has discovered that the brake lines on MY21–25 Malibu and Axis tri-axle trailers built after September 21st, 2020, may be prone to unintended stress, potentially resulting in failure during operation due to the way the brake lines were routed and secured to the axles at time of manufacture. **Affected trailers must have all their brake lines replaced with new lines in an updated configuration.**



Updated trailer brake line configuration.

Your Technical Representative will be sending you a list of affected trailers associated with your dealership. For each affected trailer, please order brake line kit PN 6841032-K.










Customers will be notified of this recall via letter.

All affected trailers **must** have their brake lines replaced and installed in the new configuration. Please carefully read and follow the work instructions provided on the next page.

When submitting the warranty claim for this bulletin, please be sure to indicate the bulletin number in the claim notes.


Please contact your Technical Representative if you have questions about this recall bulletin.

TOOLS	
DRILL + #29 DRILL BIT	BRAKE FLUID - DOT 3
DRILL BIT TO ASSIST SELF TAP SCREWS	FUNNEL
SELF TAPPING SCREWS	RAGS
SOCKET FOR SELF TAP SCREWS	CATCH CAN
(2) 5/8" WRENCHES	WHEEL CHOCKS
(2) 9/16" WRENCHES	
(1) 3/8" WRENCH AND (1) 1/2" WRENCH	
HAMMER	
SCREW DRIVER - FLAT	

PARTS	
 BOLT ON BRAKE TAB  3/16" BRAKE LINE  18" BRAKE HOSE  GALV. CLIP  PLASTIC LINE CLIP	 SELF TAPPING SCREW  METAL LINE CLIP  1 MALE 2 FEMALE BRASS FITTING  3 FEMALE BRASS FITTING

STEP #1


CHOCK THE WHEELS TO MAKE SURE THE TRAILER IS SAFE TO BE UNDER.



July 07, 2025 16:42

STEP #2

USE 3/8" WRENCH TO LOOSEN AND REMOVE THE BRAKE LINE FROM THE CALIPER FITTING. USE CATCH CAN TO CATCH ANY BRAKE FLUID THAT MAY LEAK OUT.




July 07, 2025 16:57

CALIPER

USE 1/2" WRENCH TO HOLD BRASS BLOCK, THEN LOOSEN AND REMOVE THE BRAKE LINES USING 3/8" WRENCH.

STEP #3




CALIPER

3 FEMALE BRASS BLOCK


STEP #4

USE DRILL WITH #29 DRILL BIT TO DRILL THRU POP RIVET. REMOVE BRAKE LINE.




STEP #5

ON THE PORT SIDE USE HAMMER AND FLAT HEAD SCREWDRIVER TO REMOVE THE GALV. CLIP. USE 3/8" WRENCH AND 5/8" WRENCH TO LOOSEN THE CONNECTION BETWEEN METAL BRAKE LINE AND RUBBER HOSE. **LOOSEN BUT DO NOT REMOVE THE HOSE.** REMEMBER TO RETIGHTEN AND ADD THE CLIP WHEN FINISHED.



REMOVE GALV. CLIP, THEN LOOSEN CONNECTION BETWEEN THE RUBBER HOSE AND BRASS BLOCK USING 1/2" AND 5/8" WRENCH. REMOVE THE 3-FEMALE BRASS BLOCK.

STEP #6





3 FEMALE BRASS BLOCK

REPLACE THE 3-FEMALE BRASS BLOCK WITH A 2-FEMALE 1-MALE BRASS BLOCK.

STEP #7

TURN THE MALE END TOWARDS THE OUTSIDE OF THE TRAILER



2 FEMALE, 1 MALE

STEP #8

SCREW THE MALE END OF THE RUBBER HOSE INTO THE FITTING ON THE CALIPER. SCREW THE 2-FEMALE 1-MALE BLOCK ON THE END OF THE HOSE. SCREW THE VERTICAL HOSE COMING FROM THE FRAME THRU THE BRACKET INTO THE 2-FEMALE 1-MALE BLOCK. THE HOSE SHOULD SPIN SO IT CAN BE TIGHTENED. **RE-TIGHTEN THE CONNECTION LOOSED IN STEP 5.**




July 07, 2025 11:50

STEP #9




INSTALL THE METAL BRAKE LINE INTO THE BRASS BLOCK. LOOP TO TAKE OUT ANY SLACK IN THE BRAKE LINE IN A SMOOTH LARGE RADIUS. BE SURE NOT TO KINK OR CRIMP THE LINE. DRILL PILOT HOLE WITH #29 DRILL BIT AND INSTALL METAL CLIP WITH SELF TAPPING SCREW ADD SILICONE OR SEALANT TO THREADS.




ON THE STARBOARD SIDE, MEASURE 12" FROM THE SPRINGS TO DETERMINE WHERE BOLT THE CENTER OF THE BRAKE TAB. PRE-DRILL A HOLE, THEN ATTACH BRACKET TO AXLE WITH SELF-TAPPING SCREW WITH SILICONE ON THE THREADS. INSTALL THE MALE END OF THE HOSE INTO THE CALIPER AND TIGHTEN WITH 5/8" WRENCH.

STEP #10




STEP #11

INSTALL THE METAL BRAKE LINE, LOOPING IT AS SHOWN. BE SURE NOT TO KINK IT. ROUTE THE FEMALE END OF THE RUBBER HOSE THRU THE BRACKET AND INSTALL THE GALV. CLIP ON THE METAL BRAKE LINE SIDE WITH THE TOP OF THE FLANGE FACING FORWARD. SCREW THE HOSE AND LINE TOGETHER WITH 3/8" AND 5/8" WRENCHES.



STEP #12

DRILL PILOT HOLE WITH #29 DRILL BIT AND INSTALL METAL CLIPS WITH SELF-TAPPING SCREWS WITH SILICONE ON THE THREADS. PLACE CLIPS AS SHOWN. REPEAT FOR REMAINING AXLES.



STEP #13


ONCE ALL THE LINES AND HOSES HAVE BEEN CHANGED AND TIGHTENED **ON ALL THE AXLES**, IT IS TIME TO BLEED THE BRAKES. SEE INSTRUCTIONS ON FOLLOWING PAGES.

WORK INSTRUCTIONS: MANUAL BLEEDING OF THE BRAKE SYSTEM

1. Remove the reservoir plug and fill the reservoir with brake fluid. Use DOT 3 automotive brake fluid. Follow instructions on brake fluid container. Avoid shaking brake fluid container and pour fluid slowly to minimize air entrapment. Let fluid in reservoir stand until completely free of air bubbles. *If the reservoir runs dry, the bleeding process will need to start over because it may have drawn air into the braking system. Also, be extra careful to keep the brake fluid from getting on the paint; if it does, immediately clean with soap and water.*
2. IMPORTANT: Before bleeding brake lines, bleed the main cylinder. Insert screwdriver through hole in bottom of inner member and use short pumps to pry on plunger (while holding safety release bracket up) until no air bubbles are seen coming from small hole in the bottom of the main cylinder reservoir.



3. Start bleeding procedure on the brake furthest from main actuator (rear starboard).
4. At the rear starboard brake caliper, connect a transparent bleeder hose to bleed screw fitting on wheel cylinder and submerge free end into catch can partially filled with brake fluid. Do not reuse this fluid.
5. The first person pumps the plunger slowly while holding safety release bracket up. The second person opens the bleed screw fitting, then closes the bleed screw fitting BEFORE the first person SLOWLY releases the plunger. Repeat this procedure until the fluid expelled from the bleeder hose is free of air bubbles. Remember to always tighten the bleeder screw before releasing plunger. During this procedure, the reservoir fluid level must be maintained at no less than 1/2 full.



6. Repeat steps 4 and 5 for opposite side caliper, then move on to next axle up.
7. Bleed all calipers again, repeating Steps 3–6, to ensure all air is purged from the system.
8. As a final check after bleeding is completed, pump the plunger and verify pressurization of the brake system by attempting to rotate a tire.
9. Push up on the safety release bracket to ensure that plunger is in released position.
10. After bleeding has been completed, re-check fluid level in main cylinder. Fill the master cylinder reservoir up to indicator on reservoir plug. Do not overfill.

STEP 1

Work Instructions - Bleeding Brake System w/ Portable Hand Bleeder



**BE CAREFUL WITH BRAKE
FLUID IT IS CORROSIVE TO
PAINT AND SLIPPERY WHEN
ON CONCRETE. MAKE
EVERY EFFORT TO BE SAFE.**

STEP 2


**REMOVE THE OUTER CAP TO GAIN
ACCESS TO THE ACTUATOR
RESERVOIR**

TO PROTECT THE
PAINT, TAKE AN
OLD PIECE OF
CLOTH AND CUT A
2" HOLE IN THE

STEP 3



CENTER



PRY THE RUBBER
CAP LOOSE WITH A
FLAT HEAD SCREW
DRIVER. THEN
REMOVE THE CAP.



PLACE THE CLOTH ON THE
ACTUATOR AROUND THE
OPENING




STEP 4


REMOVE THE PORTABLE HAND BLEEDER
FROM THE BOX.




STEP 5

REMOVE THE CAP AND FILL
WITH BRAKE FLUID UP TO THE
BOTTOM OF OF THE NECK. BE
CAREFUL NOT TO OVER FILL IT.
YOU MUST LEAVE ROOM FOR
THE PUMP





HAVE A RAG READY TO CATCH THE FLUID.




STEP 8



PLACE THE RUBBER TIP IN THE RESEVOIR ACCESS HOLE.

STEP 9

THE CLAMP WILL NEED TO BE ADJUSTED TO FIT THE ACTUATOR BEING BLED. SEE THE HOLE LOCATION FOR XR-84 (8400 X 2" BALL) ACTUATOR



August 11, 2025 07:31

STEP 10

THIS LOCATION FITS THE A160 16K 2-5/16" ACTUATOR

August 08, 2025 08:19

STEP 11


MAKE SURE THE HOSE DOESN'T PINCH CLOSE

ONCE THE CLAMP HAS BEEN ADJUSTED
USE THE SCREW AT THE BOTTOM FOR
FINAL ADJUSTMENT. THE CLAMP DOESN'T
NEED TO BE EXTREMELY TIGHT.

August 08, 2025 08:18

STEP 12


ONCE THE BOTTOM SCREW HAD BEEN ADJUSTED, THE CLAMP IS READY TO BE INSTALLED. **BE CAREFUL NOT TO OVER TIGHTEN OR IT MAY PUSH THE RESERVIOR SEAL INTO THE RESERVIOR**



August 08, 2025 03:19

1. TURN ON THE BRAKE FLUID.
2. BUBBLE MAY BE SEEN BUT AS LONG AS BRAKE FLUID CAN PASS BY ITS NOT AN ISSUE.
3. KEEP AN EYE ON THE HOSE THAT IT IS NOT KINKED AT THE FITTING.

STEP 13



August 08, 2025 08:20

STEP 14





BLEED THE BRAKE SYSTEM:

THE BLEEDER ON THE CALIPER THATS THE FARTHEST AWAY FROM THE ACTUATOR. BE SURE TO CATCH THE FLUID, A FUNNEL MAY BE NEEDED.
COME OUT IN THE TIME IT TAKES TO SAY A SLOW 10 COUNT.
OUT OF THE BLEEDER START THE 10 COUNT OVER AGAIN.
STARTING WITH THE NEXT FARTHEST AWAY FROM THE ACTUATOR

1. OPEN
2. ALLOW FLUID TO
3. IF AIR BUBBLES COME
4. DO THIS TO EACH CALIPER

STEP 15




ONCE ALL THE CALIPERS HAVE BEEN BLED. TURN OFF VALVE.

August 08, 2025 08:22

STEP 16



RELEASE THE CLAMP




STEP 17


REMOVE THE CLAMP. TAKE YOUR TIME REMOVING IT AND BE CAREFUL BRAKE FLUID WILL DRIP FROM THE NOZZLE.



FLUID LEVEL INDICATOR: ON THE RESERVOIR CAP THERE IS A DIP STICK WHICH MEASURES THE BRAKE FLUID LEVEL. IT SHOULD BE BETWEEN THESE TWO POINTS. AFTER REMOVING THE BLEEDER THE FLUID LEVEL COULD BE TOO HIGH SO SOME FLUID WILL NEED REMOVED. A TURKEY BASTER WORK GREAT. THE CORRECT LEVEL OF FLUID WILL KEEP IT FROM SPILLING OVER WHEN THE CAP IS REINSTALLED.

STEP 18





August 08, 2025 08:23

